

Oil Field Environmental Incident Summary

Incident: 20160107115309 **Date/Time of Notice:** 01/07/2016 11:53

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: GUY FEDERAL 24X-35F

Field Name: GRINNELL

Well File #: 27516

Date Incident: 1/6/2016 **Time Incident:** 05:30

Facility ID Number:

County: MCKENZIE

Twp: 154

Rng: 97

Sec: 35

Qtr:

Location Description: Majority of fluid stayed on well pad. Light mist sprayed WSW off location onto landowner property.

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	8	Barrels	8	barrels
Brine	7	Barrels	6	Barrels	6	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/24/2016

Clean Up Concluded: 1/21/2016

Risk Evaluation:

None- well was shut in at time of discovery and no injuries occurred.

Areal Extent:

Affected area approximately 725' x 550' WSW of pad.

Potential Environmental Impacts:

Minimal- Well pad soil was affected on location. Off the pad, snow and minimal vegetation was affected WSW off location.

Action Taken or Planned:

The well was shut in immediately at time of discovery. Cleanup started after landowner notification and approval. The impacted material will be removed and hauled to an approval disposal facility. The adjustable choke and associated piping will be replaced.

Wastes Disposal Location: To be determined...

Agencies Involved:**Updates**

Date: 1/7/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release misted off sight. Further followup needed.

Date: 1/12/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 13:30 p.m. Cleanup crew was at location cleaning up the release that remained on the well pad. The release sprayed off of the west/southwest side of the pad. There is another XTO pad that is located on the hill (Flatland). There was evidence of oil midway up the perimeter of that well pad and to the second utility pole. Some oil residue was found across the access road. The release misted into the farmer's field as well. Contact will be made with XTO to clarify a cleanup plan. Photos can be found in the report folder. Further followup necessary.